ZE5629 D4376



SDMS DociD

ociD 2198347

FINAL

PRELIMINARY ASSESSMENT FOR THE FRED'S AUTO JUNKYARD SITE LOWER PROVIDENCE TOWNSHIP, MONTGOMERY COUNTY, PENNSYLVANIA DUMP SITE NO. PA-3017 EPA ID NO. PAD987378213

EPA WORK ASSIGNMENT NO. 85-12-3JZZ CONTRACT NO. 68-W8-0085

December 1993

Prepared for:

HAZARDOUS WASTE MANAGEMENT DIVISION U..S. Environmental Protection Agency

Prepared by:

Ecology and Environment, Inc. Philadelphia, Pennsylvania



ecology and environment, inc.

International Specialists in the Environment

140 West Germantown Pike, Plymouth Meeting, Pennsylvania 19462 Tel: 215/832-1370, Fax: 215/832-2110

PRELIMINARY ASSESSMENT FOR THE FRED'S AUTO JUNKYARD SITE LOWER PROVIDENCE TOWNSHIP, MONTGOMERY COUNTY, PENNSYLVANIA DUMP SITE NO. PA-3017 EPA ID NO. PAD987378213

EPA WORK ASSIGNMENT NO. 85-12-3JZZ CONTRACT NO. 68-W8-0085

December 1993

Prepared for:

HAZARDOUS WASTE MANAGEMENT DIVISION U.S. Environmental Protection Agency

Prepared by:

Ecology and Environment, Inc. Philadelphia, Pennsylvania

~ E & E Task Leader

Data

TABLE OF CONTENTS

Section	i		Page
1,			1-1
v	1.1	AUTHORIZATION	1-1
•	1.2	SCOPE OF WORK	, 1-1
* 1	1.3	SUMMARY	1-2
2	SITE	E DESCRIPTION	2-1
**	2.1		2-1
	2.2	SITE LAYOUT	2-1
,	2.3	SITE OWNERSHIP	2-3
	2.4	SITE USE HISTORY	2-3
• ; ;	2.5	PERMIT AND REGULATORY HISTORY	2-4
•	2.6	REMEDIAL ACTION TO DATE	2-4
·			Ē
3	ENV	TRONMENTAL SETTING	3-1
	3.1	WATER SUPPLY	3-1
	3.2	SURFACE WATER	3-3
	3.3	HYDROGEOLOGY	3-3
		3.3.1 Geology	3-4
		3.3.2 Soils	3-5
	:	3.3.3 Groundwater	3-5
, c	3.4	CLIMATE AND METEOROLOGY	3-5

Table of Contents (Cont.)

Section		Page
	3.5 LAND USE	3-6
	3.6 POPULATION DISTRIBUTION	3-6
	3.7 CRITICAL ENVIRONMENTS	3-7
4	WASTE TYPES AND QUANTITIES	4-1
,		• •
5	FIELD TRIP REPORT	5-1
	5.1 PERSONAL INTERVIEWS CONDUCTED	5-1
i i	5.1.1 Prior to Site Visit	5-1
	5.1.2 During the Site Visit	5-2
5위 * 1위, 1	5.1.3 Homewell Survey Form Distribution	5-2
6	REFERENCES	6-1
Appendices		•
Appendices	PHOTOGRAPHIC LOG	A-1
В	EPA FORM 2070-12	B-1
C	ANALYTICAL RESULTS FOR AREA HOMEWELLS	C-1

LIST OF ILLUSTRATIONS

<u>Figure</u>	The state of the s		Page
2-1	SITE LOCATION MAP		2-6
2-2	SITE LAYOUT MAP	21°	2-7
3-1	FOUR-MILE RADIUS MAP	• • • • •	Back Pocke

1. INTRODUCTION

1.1 AUTHORIZATION

The Preliminary Assessment (PA) of the Fred's Auto Junkyard (Fred's Auto) site was performed by Ecology and Environment, Inc. (E & E) under contract number 68-W8-0085 for the United States Environmental Protection Agency (EPA), Region III, Alternative Remedial Contracting Strategy (ARCS), EPA Work Assignment No. 85-12-3JZZ. This PA was conducted under the authority of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 (CERCLA) and the Superfund Amendments and Reauthorization act of 1986 (SARA).

1.2 SCOPE OF WORK

The subject of this CERCLA PA investigation is the site of an automobile repair shop, scrap yard, and commercial auto salvage yard located in Lower Providence Township, Montgomery County, Pennsylvania. The purpose of the investigation was to collect information concerning conditions at this site sufficient to assess the threat posed to human health and the environment, and to determine the need for additional action. The scope of the investigation included a review of available file information, interviews with people knowledgeable of previous activities at the site, a comprehensive target survey, and a site reconnaissance visit. Appendix A presents a photographic record of the site visit performed by E & E, Appendix B presents EPA Form 2070-12, and Appendix C presents analytical data associated with homewell samples collected in the study area.

1.3 SUMMARY

The Fred's Auto site is located at 2650 Egypt Road in Lower Providence Township, Pennsylvania. The approximately 4-acre, nearly square site includes a residence, an automobile repair shop, the Crusher-One automobile salvage yard, and a small scrap yard. The repair shop has been operated by Fred Melchiorre since approximately 1955. Crusher-One, a commercial automobile salvage yard, has been operated on site since 1992. The residence has been occupied by various tenants since some time prior to 1950. On-site operations include automobile repair and maintenance, and the crushing of abandoned automobiles using a mobile crushing machine (Ref. 2).

Waste materials currently generated on site include spent automotive motor oil from the auto repair service and used automotive air filters. Waste motor oil is burned as heating oil for the repair garage, and used automotive oil filters from the automobile repair service are burned with other refuse in drums in an area near the garage. A cold solvent parts cleaner was used in the garage from 1963 to 1978. The solvent was reportedly reclaimed by Safety Kleen, a solvent delivery and recycling service, in 1978 (Ref. 2).

Residents within a 4-mile radius of the site receive potable water from community water supply companies and homewells. Several community supply wells owned by the Audubon Water Company (AWC) and homewells in the site study area were found to contain trichloroethylene (TCE) in concentrations exceeding the maximum concentration limit (MCL) of 5.0 μ g/L. The homewell that serves the on-site residence was reportedly sampled several years ago and volatile organic compounds (VOCs) were not detected; however, documentation for this sampling event is not available (Refs. 1, 2, 3, 4).

One source of TCE in groundwater in the area has been identified as the Commodore Semiconductor Group (CSG) manufacturing facility, located approximately 0.45 mile south of the site. The CSG facility is on the National Priorities List (NPL). Studies of groundwater flow in the area indicate that the CSG site may not be the sole source of TCE detected in the area wells (Refs. 6, 7, 8).

On August 26, 1993, and and of E & E conducted an inspection of the Fred's Auto site. The field team was accompanied on site by Fred Melchiorre of Fred's Auto Service. No representative of Crusher-One was present during the inspection. The field team observed site conditions and spoke to nearby residents regarding TCE contamination in their wells (Ref. 2).

2. SITE DESCRIPTION

2.1 SITE LOCATION

The Fred's Auto site is located at 2650 Egypt Road in Lower Providence Township, Montgomery County, Pennsylvania (see Figure 2-1). Coordinates for the approximate center of the site are 40°07'45" north latitude and 75°24'45" west longitude. The site can be located by measuring 3/4-inch north and 5-1/4 inches west from the southeast corner of the United States Geological Survey (USGS) 7.5-Minute Series map for the Collegeville, Pennsylvania quadrangle (Ref. 1).

2.2 SITE LAYOUT

The 4-acre, nearly square Fred's Auto site includes a residential property, a garage/automobile repair shop, the Crusher-One automobile salvage yard, and a small scrap yard. The residential property and automobile repair shop are located approximately 50 feet south of Egypt Road, and the Crusher-One automobile salvage yard is located behind the residential property and automobile repair shop. The scrap yard is located adjacent to Egypt Road, east of the automobile repair shop.

The site is sloped to the south. Runoff from all areas of the site flows downgradient toward fields located south of the site. The ground surface on the residential property and scrap yard areas is covered with long grass. The ground surface in the garage and burn pit area is covered with patches of short grass. The ground surface in the automotive salvage yard area consists of compacted dirt with some gravel (Ref. 2).

Egypt Road forms the northern site boundary, and undeveloped property is located north of Egypt Road. An apple orchard is located immediately south of the site, and a corn field bounds the site to the west and to the east (Ref. 2)

On-Site Residence

The on-site residence is a two-story, single-family home constructed prior to 1950. The on-site residence is served by a homewell drilled in approximately 1975. Another well was drilled when the house was constructed, but this older well is no longer used. Reportedly, the older well became dry when wells were installed for the Washington Country Club golf course, located 0.25 mile west of the site. Wastewater from the house is disposed of through a cesspool located in the back yard downgradient of the wells. Currently, the house is occupied by three persons (Refs. 2, 22).

Garage/Automobile Repair Shop

The automobile repair shop includes a double garage equipped with various tools and equipment for automotive repair and maintenance, a small yard where cars to be repaired are parked, a small shed, a drum storage area, and a burn pit (Ref. 2).

The garage is approximately 75 feet by 25 feet and 10 feet high. The floor is made of concrete. The garage contains equipment for the automobile repair shop including a 125-gallon-capacity cold solvent parts cleaner. This unit is identified as a Magnus Chemical, Model MIJI, LIF, manufactured by Magnus Chemical of Plainfield, New Jersey. The unit is inactive and is reported to contain no solvents (Ref. 2).

During E & E's site visit, eleven 55-gallon steel drums and one steel 200-gallon heating oil storage tank were located on an elevated rack in the drum storage area on the east side of the garage. The waste oil was stored and designated as fuel for the heating system during the winter. No evidence of leakage from the drums was observed (Ref. 2).

A small burn pit is located south of the garage. Five rusted, open 55-gallon drums are present in this area. General refuse, such as used automotive oil filters, is occasionally burned inside the drums prior to disposal. Ashes were observed on the ground in this area (Ref. 2).

Salvage Yard

An 80-foot by 30-foot scrap yard is located approximately 100 feet northeast of the garage. The scrap yard contains several abandoned cars and a pair of abandoned steel tanks. The prior use of the tanks is unknown. The tanks were empty at the time of the E & E site visit (Ref. 2).

Crusher-One Automobile Salvage Yard

The 3-acre Crusher-One auto salvage yard is located approximately 100 feet south of the garage. An approximately 4-foot-high wooden fence surrounds this area. Abandoned cars and trailers are stored here prior to being crushed on site and sold for scrap. A mobile automobile crushing machine is occasionally brought to a 50-foot by 50-foot area in the southwest corner of the yard to crush the automobiles for salvage. The unit was not on site at the time of the E & E site visit, and neither stained soils nor evidence of leaked or spilled fluids was observed (Ref. 2).

2.3 SITE OWNERSHIP

Currently, the site is owned by Neilson Real Estate of Norristown, Pennsylvania. Fred Melchiorre has leased the automotive repair garage and burn pit areas since 1955. According to Fred Melchiorre, the site has been owned by Neilson Real Estate since some time prior to 1955. Previous site owners are unknown. The automotive salvage yard has been leased to the proprietors of Crusher-One for approximately one year. The residential property has been leased to various persons since some time prior to 1950. The items in the scrap yard east of the driveway belong to Neilson Real Estate (Ref. 2).

2.4 SITE USE HISTORY

Fred Melchiorre has operated his automotive repair shop since 1955. Prior to 1955, the site was leased by another tenant who reportedly fixed and sold used automobiles. In approximately 1960, Mr. Melchiorre purchased and installed a cold solvent parts cleaner. The nature of the solvent within the unit is not known. Mr. Melchiorre reportedly never drained the solvent from the parts cleaner until 1978. At that time, he hired Safety Kleen to drain the unit and reclaim the solvent. The parts cleaner has been empty since 1978 (Ref. 2).

According to Mr. Melchiorre, the Crusher-One automobile salvage yard was developed in 1992. Currently, the yard is used to store abandoned automobiles and it is used as a staging area for a mobile automobile crusher to prepare the cars for reclamation off site (Ref. 2).

A 1965 aerial photograph of the site indicates that the area which is now the Crusher-One auto salvage yard may have been occupied by abandoned cars. A 1970 aerial photograph shows this area as vegetated and unused. No other changes in land use on site appear in the aerial photographs (Refs. 3, 4).

2.5 PERMIT AND REGULATORY HISTORY

No records of site inspections by the Pennsylvania Department of Environmental Resources (PADER) or environmental violations at the Fred's Auto site have been found. EPA, PADER, AWC, and CSG are currently investigating homewells on Audubon Road, Egypt Road, and Rittenhouse Road, and municipal wells in the Valley Forge Corporate Center and other areas of Lower Providence Township. TCE, a commonly used industrial solvent, is the primary contaminant of concern detected in these wells.

Groundwater investigations in the site area are summarized below:

1978	TCE is detected in municipal supply well VFCC-2/24 owned by AWC. PADER determines that the CSG facility located 0.45 mile southwest of the Fred's Auto site is the probable source of TCE.
1984	CSG purchases an air stripper to treat water from AWC well No. VFCC24 and purchases carbon filters to treat water from 24 nearby homewells.
1986	EPA begins an investigation of the CSG site.
1989	The CSG site is included on the NPL for remediation.
1988	TCE is detected in AWC well nos. 6 and 9. These wells are located approximately 0.8 mile north of the CSG site and 0.8 mile northwest of the Fred's Auto site. The source of TCE detected in these wells has not been positively identified (Refs. 1, 5).
1992	A Remedial Investigation and Feasibility Study (RI/FS) conducted by a consultant hired by CSG is completed. The RI/FS determines that groundwater in the vicinity of the CSG site flows south. This suggests that the CSG site may not be the source of TCE detected in AWC well No. 6, No. 9, or in some of the houses on Rittenhouse Road (Refs. 5, 6). (See Appendix D for figures from the RI/FS which illustrates the extent of TCE contamination of

2.6 REMEDIAL ACTION TO DATE


No remedial actions have been performed at the Fred's Auto site, and no spills or releases of hazardous waste are known to have occurred. Since 1981, EPA, PADER, AWC, and CSG have worked to address TCE contamination of local drinking water supplies.

of contaminants from the CSG site.) (Ref. 7).

drinking water that exceeds the MCL, and for a hypothesized migration route

However, the source of TCE detected in AWC well No. 6 and No. 9 and in some of the houses on Rittenhouse Road has not been positively identified (Refs. 6, 7, 8).

The RI/FS work plan developed by Roy F. Weston, Inc. for CSG included a summary of homewell sample results collected by PADER (see Appendix C). The Fred's Auto site well is not included in this summary. According to Mr. Melchiorre, the on-site well was tested several years ago after TCE was detected in the AWC wells and the on-site well did not show contamination by VOCs; however, he did not retain a copy of the analytical results and cannot recall who collected the sample (Refs. 1, 2, 8).



SOURCE: USGS 7.5 Minute Series (Topographic) Quadrangle: Collegeville, PA 1966 Photorevised 1983, Valley Forge, PA 1966 Photorevised 1981





Figure 2-1 SITE LOCATION MAP, FRED'S AUTO JUNKYARD



Figure 2-2 SITE LAYOUT MAP, FRED'S AUTO JUNKYARD

3. ENVIRONMENTAL SETTING




02:ZE5629 D4376-12/13/93-D1

3-1

recycled paper

ecology and environment



3.2 SURFACE WATER

Drainage from the site flows south by southeast onto the orchard and corn field behind the site, then flows generally eastward and enters Indian Creek approximately 4,500 feet downgradient from the southeast corner of the site. This point is assumed to be the probable point of entry (PPE) of sediment and runoff from the site. Indian Creek flows

approximately 1.1 miles to the Schuylkill River, which flows south and east toward Philadelphia. The 15-mile downstream target distance extends to a location 0.2 mile upstream of the City Avenue Bridge on the Schuylkill River:

Indian Creek and the Schuylkill River are warmwater fisheries. The Schuylkill River provides habitat for migratory fishes. PAWSC maintains a surface water intake on the Schuylkill River approximately three miles downstream from the PPE, on Barbados Island. This intake serves approximately 79,000 residents in Montgomery County. The Schuylkill River has an average discharge of 2,922 cubic feet per second (cfs) measured near the Fairmount Dam in Philadelphia. Discharge information pertaining to Indian Creek is not available (Refs. 1, 2, 19, 20).

3.3 HYDROGEOLOGY

The geologic and hydrogeologic conditions in the study area were researched as part of the site investigation. A preliminary literature review was conducted to determine surface and subsurface geologic conditions, soil character, and the status of groundwater transport and storage.

3.3.1 Geology

The Fred's Auto site is located within the Triassic Lowlands section of the Piedmont physiographic province, near its border with the Piedmont Uplands Section. The rocks of the Triassic section are commonly known as the Newark group, a 16,000- to 20,000-foot section of nonmarine sedimentary rocks and associated intrusive and extrusive basic rocks. The Newark group was deposited in the Newark Basin, which was part of a rift system initiated by the widening of the Atlantic Basin and separation of the continents in Mesozoic time.

The Piedmont Uplands section of the Piedmont physiographic province is present beneath the southern portion of the study area, and it consists of Precambrian- to Ordovician-age metamorphic and igneous rocks. The site area has a dendritic geomorphic drainage pattern and a topography of broad, shallow valleys and rolling hills (Refs. 1, 12, 13).

The site is directly underlain by the Triassic-age Stockton formation. The Stockton formation is composed of a lower arkosic conglomerate member, a middle arkosic sandstone member, and an upper mudstone member. The lower yellow-gray conglomerate deposits consist of poorly sorted, moderately rounded clasts of quartz, quartzite, limestone, and feldspar. The clasts average 1 inch in diameter and are set in a poorly sorted arkosic matrix.

The middle sandstone member is a fine- to medium-grained, light yellowish-gray to pale reddish-brown, fairly well sorted arkosic sandstone. The upper mudstone is reddish-brown in color and is feldspathic. The abundant feldspar in the Stockton formation implies a continuous supply from a soda-rich, metamorphosed Paleozoic source east and south of the Newark Basin. The erosion of these crystalline eastern and southern highlands spread Stockton sediments across the basin, forming extensive flood plain deposits. Fossil fauna such as ferns, conifers, ginkos, mollusks, labyrinthodont amphibians, and phytosaur reptiles suggest an extensive fluvial and flood plain paleoenvironment for the Stockton. The thickness of the formation reaches a maximum of 6,000 feet at the Montgomery-Bucks county line (Refs. 12, 13).

The Stockton formation is overlain by the Triassic-age Lockatong formation, which contacts the Stockton 0.75 mile north of the site. The Lockatong is a dark gray to black argillite with zones of black shale and thin layers of impure calcareous shale. The unit is moderately well bedded with flaggy to thick beds. Joints have a blocky pattern and are moderately well developed, closely spaced, steeply dipping, and open (Refs. 12, 13).

The Triassic Lowlands contact the Piedmont Uplands approximately 2.0 miles south of the site. Although the topography is similar, rock character changes radically. The rocks of the Piedmont Uplands are predominantly metamorphic and igneous schists, quartzites, and granites (Refs. 13, 18).

Discordant, basin-shaped sheets and cross-cutting dikes of diabase intruded the Newark group in late Triassic time; therefore, their stratigraphic position varies throughout the study area. A prominent dike of diabase is located 3.25 miles west of the site. Diabase is dark gray to black, dense, and very fine grained, and consists of 90% to 95% labradorite and augite. These olivine-poor diabase rocks are characteristic of rift valley sequences and were emplaced during episodes of tensional rifting associated with the opening and widening of the Atlantic Basin. The dikes are generally 5 to 100 feet thick, while the sheets are much thicker (Refs. 12, 13).

3.3.2 Soils

Soils on site are classified as Penn-Lann loam with 3% to 8% slope. This soil is formed from weathered red shale, yellowish brown sandstone, and siltstone. Permeability of this soil is moderate to moderately rapid, surface runoff is rapid, and the hazard of erosion is severe (Ref. 17).

3.3.3 Groundwater

In the Stockton formation, the lower conglomerate member and the middle arkosic sandstone member contain primary and secondary openings that provide a moderate to high total effective porosity and permeability. The middle arkosic sandstone has the highest average reported yield, 131 gallons per minute (gpm), and the highest average specific capacity of any of the formation members, 4.8 gpm per foot. The lower conglomerate member has an average specific capacity of 3.1 gpm per foot. The upper mudstone member is too finely grained to allow for permeability sufficient to permit easy circulation of groundwater. Most wells tapping this member obtain water chiefly from fractures and joints. This upper mudstone has an average reported yield of 19 gpm and an average specific capacity of 0.4 gpm per foot. All the formations in the study area are likely to be hydraulically interconnected through fractures and joints (Ref. 12).

The diabase has a very low secondary porosity and a low permeability. Well yields in Montgomery County range from 0.3 to 35 gpm, with a median yield of 5 gpm. Diabase is a poorly yielding aquifer. Most wells obtain their yields from a depth of 50 feet or less, and the maximum depth from which a well in diabase is reported to obtain water is 125 feet. The average specific capacity is less than 1 gpm per foot (Ref. 12).

3.4 CLIMATE AND METEOROLOGY

The Philadelphia city limits are located approximately 10 miles east of the site. Climatological data was obtained for Philadelphia, Pennsylvania, based on the period from 1951 to 1980. According to these data, the average annual temperature is 54.3°F. The coolest month is January, with a mean temperature of 31.2°F; the hottest month is July, with a mean temperature of 76.5°F (Ref. 15). The average annual precipitation is 41.42 inches. The month with highest precipitation is August, with 4.10 inches; the month with lowest precipitation is February, with 2.81 inches. The 2-year, 24-hour rainfall event produces 3.0 inches of rain. The mean annual lake evaporation for the area is 34.5 inches. Therefore, the net precipitation gain is 6.92 inches (Ref. 15).

The annual prevailing wind direction is from the west-southwest. Southwesterly winds prevail during the summer months, while northwesterly winds prevail during the winter. Destructive velocities are comparatively rare, and most gusts occur during summer thunderstorms (Ref. 15).

3.5 LAND USE

The Fred's Auto site is located in an area of mixed residential, commercial, industrial, and agricultural development. The areas immediately surrounding the site consist largely of agricultural properties. The Valley Forge Corporate Center is located approximately 0.25 mile south of the site and contains many small industries and businesses. Two Superfund sites are located nearby: Moyer Landfill, EPA identification No. PAD980508766, is located approximately 2 miles northwest of the site, and CSG, EPA identification No. PAD0937301-74, is located approximately 0.45 mile south-southeast of the site. Areas north and west of the site are dominated by residential and commercial developments (Refs. 1, 2, 15).

3.6 POPULATION DISTRIBUTION

A number of towns and communities in Montgomery and Chester counties are located within the 4-mile radius study area of the site. Population counts within discrete radii identified on the 4-mile radius map appear below (see Figure 3-1):

Radius (Miles)	n .		Approx	kimate Popu
On-Site				3
0 to 0.25 mile 0.25 to 0.5 mile	147			46 450
0.25 to 1 mile		Ť.		1,600
1 to 2 miles				6,200
2 to 3 miles 3 to 4 miles	7.* 	Service of the servic	lin .	8,500 <u>14,400</u>
Total	er en	Alam Maria		31,199

The data presented for distance intervals are not cumulative. Population estimates are based on a house count as identified on the 4-mile radius map where possible, multiplied by a persons-per-household average of 2.58 for Montgomery County and 2.73 for Chester County. For communities in which individual houses are not identified, the total population of the affected community was calculated by multiplying the approximate portion of the community area occurring within the distance interval by 2,140.4 persons per square mile, the appropriate population density for Norristown, Pennsylvania. These communities are Trooper, West Norriton, Jeffersonville, Norristown, Brandywine Village, Belmont Terrace, and Bridgeport (Refs. 1, 2, 11).

3.7 CRITICAL ENVIRONMENTS

According to information obtained from the United States Fish and Wildlife Service (USFWS) and the Pennsylvania Game Commission, the following endangered species potentially occur in the study area: the bald eagle (Haliaeetus leucocephalus), the peregrine falcon (Falco peregrinus), the Redbelly Turtle (Chrysemys rubiventris), the Indiana Bat (Myotis sodalis), and the small Whorled Pogonia (Isotria medeoloides). The bald eagle and the peregrine falcon are transient species (Refs. 16, 14). The Schuylkill River is a warmwater fishery which provides habitat for migratory fishes (Ref. 20).

There are approximately 6.5 acres of wetlands within a 1-mile radius of the site. These wetlands occur along the banks of Indian Creek and are denoted as palustrine, forested, temporary wetlands (Ref. 21). This area receives runoff from the site. There are also some palustrine, broad-leaf, deciduous forested, temporary wetlands located along the Schuylkill River within 15 river miles of the PPE (Refs. 1, 14, 21).

A summary of estimated wetland frontage along the surface water migration pathway and wetland acreage within a 1-mile radius of the site follows (Ref. 21):

Stream Miles from PPE	Wetland Fro	ntage (miles)
0 1.6 3.6 9.3 10.2		1.1 0.15 0.1 0.15 0.4
Total (estimate)		1.9
Distance from Site (Miles)	Wetland Ac	reage
On site 0 to 0.25 0.25 to 0.5 0.5 to 1.0	0 0 0 6	
Total (estimate)	6	

4. WASTE TYPES AND QUANTITIES

Waste materials currently generated at the Fred's Auto site include spent automotive motor oil, oil filters, and other miscellaneous wastes generated by Fred's Automotive Repair Service. Spent oil is accumulated in drums on site and burned for heat during the winter. Approximately 70 gallons of waste oil were stored on site during the E & E site visit. Waste oil filters are burned with other refuse in a drum in the burn pit behind the garage.

In approximately 1978, Mr. Melchiorre hired Safety Kleen to reclaim approximately 135 gallons of solvent from a parts cleaner on site. The type of solvent reclaimed from the unit is unknown (Ref. 2).

No waste materials were observed in the area of the Crusher-One automobile salvage yard. A small scrap yard east of the garage contains seven abandoned cars, and two abandoned aboveground metal mixing tanks. No evidence of disposed liquids or buried waste materials were observed on site.

5. FIELD TRIP REPORT

On August 26, 1993, and and of E & E performed a site reconnaissance visit at the Fred's Auto site. They met with Fred Melchiorre of Fred's Autobody and discussed site history and current uses of the site.

The E & E field team walked through all areas of the site to identify potential hazards, site features, and site utilities (see Appendix A). An organic vapor analyzer (OVA) was used to monitor the concentration of VOCs in ambient air, and a radiation meter was used to monitor radionuclides in ambient air. No readings above background were recorded on either instrument (Ref. 2).

Following the site reconnaissance, the E & E field team visited several homeowners in the area to determine homewell locations. Residents at 826, 829, and 835 Rittenhouse Road reported that their wells are contaminated with TCE and are no longer used for drinking water. Each resident reported that a new well had been installed on their property when the Washington County Club golf course wells were constructed. A homewell survey form was distributed to each of these residents, and a survey form was left at 839 Rittenhouse Road. None of the homewell surveys was returned to E & E.

5.1 PERSONAL INTERVIEWS CONDUCTED

5.1.1 Prior to Field Trip

The following persons were interviewed before E & E's August 26, 1993 site visit:

Dave Rittenhouse Neilson Real Estate 2650 Egypt Road Norristown, PA 19403 215/631-1100

Ruth Rzepski USEPA Region III 215/597-3216

Fred Melchiorre Fred's Auto Service 2650 Egypt Road Norristown, PA 19403 215/666-6105

5.1.2 During the Site Visit

The following person was interviewed during E & E's August 26, 1993 site visit.

Fred Melchiorre Fred's Auto Service 2620 Egypt Road Norristown, PA 19403 215/666-6105

5.1.3 Homewell Survey Form Distribution

Homewell survey forms were distributed to the following addresses during E & E's August 26, 1993 site visit.



6. REFERENCES

- United States Geological Survey (USGS), 7.5-Minute Survey topographical maps for Collegeville, Pennsylvania 1966, photo revised 1983; Valley Forge Pennsylvania 1966, photorevised 1981; Lansdale, Pennsylvania 1966, photorevised 1983; Norristown, Pennsylvania 1966, photorevised 1983.
- 2. Ecology and Environment, Inc. (E & E), August 26, 1993, Field Logbook for Fred's Auto Junkyard Preliminary Assessment, PA-3017, Philadelphia, Pennsylvania.
- 3. Montgomery County Planning Commission, 1985, aerial photograph plate A27/B43.
- 4. Montgomery County Planning Commission, 1970, aerial photograph, plate A27/B43.
- 5. Environmental Protection Agency, undated, Proposed Plan, Commodore Semiconductor/MOS site. Lower Providence Township, Pennsylvania, Philadelphia, Pennsylvania.
- 6. Rzepski, Ruth, September 16, 1993, USEPA Remedial Project Manager. telephone conversation with Donovan Robin, Ecology and Environment, Inc., Philadelphia, Pennsylvania.
- 7. R.F. Weston, Inc., July 1992, Remedial Investigation and Feasibility Study at the Commodore Semiconductor Facility, prepared for Commodore Semiconductor Group.
- 8. R.F. Weston, Inc., January 1989, Work Plan for Remedial Investigation at the Commodore Semiconductor Group Facility, prepared for Commodore Semiconductor Group.
- 9. Montgomery County Planning Commission, 1992, Water Supply Facilities, Status Report 1990.
- 10. Montgomery County Planning Commission, 1992, Montgomery County, Pennsylvania, Existing Water Facilities Map.

- 11. United States Department of Commerce, Bureau of the Census, August 1991, 1990 Census of Population and Housing, Summary of Population and Housing Characteristics, Pennsylvania.
- 12. Pennsylvania Department of Environmental Resources (PADER), Bureau of Topographic and Geologic Survey, 1982, Engineering Characteristics of the Rocks of Pennsylvania, Environmental Geology Report No. 1.
- 13. Pennsylvania Department of Environmental Resources (PADER), Bureau of Topographic and Geologic Survey, 1981, Atlas of Preliminary Geologic Quadrangle Maps of Pennsylvania, Map No. 61.
- 14. United States Department of Interior, Fish and Wildlife Service (FWS), 1992, Federally Listed Endangered Species in Pennsylvania.
- 15. National Oceanic and Atmospheric Administration (NOAA), 1979, Annual Summary with Comparative Data, Philadelphia, Pennsylvania, Climatography of the United States, Local Climatological Data, National Climatic Data Center, Asheville, North Carolina.
- 16. Pennsylvania Game Commission, 1992, Pennsylvania Fish and Wildlife Data Base, List A: Endangered and Threatened Species.
- 17. United States Department of Agriculture (USDA), Soil Conservation Service (SCS), April 1967, Soil Survey of Montgomery County, Pennsylvania.
- 18. Pennsylvania Department of Environmental Resources (PADER), Bureau of Topographic and Geologic Survey, 1987, Outstanding Scenic Geological Features of Pennsylvania, Environmental Geology Report No. 7, Part 2.
- 19. United States Geological Survey, 1991, Water Resources Data, Pennsylvania, Water Year 1990, Volume 1, LeRoyne, Pennsylvania.
- 20. Pennsylvania Department of Environmental Resources, August 1991, Pennsylvania Code, Title 25: Environmental Resources, Water Quality Standards.
- 21. United States Department of the Interior, No Date, Wetland Inventory Maps for the Collegeville, Pennsylvania; Valley Forge, Pennsylvania; and Germantown, Pennsylvania quadrangles. Newton Corner, Massachusetts.
- 22. Polinsek, October 27, 1993, Eagle Realty, Norristown, Pennsylvania, telephone conversation with D. Robin, Ecology and Environment, Inc., Philadelphia, Pennsylvania.

ORIGINAL (Red)

APPENDIX A

PHOTOGRAPHIC LOG





PHOTO LOCATION MAP, FRED'S AUTO JUNKYARD Figure A-1


ecology and environment, inc. PHOTOGRAPHIC RECORD		
Client: EPA Region III	E & E Job No.: ZE5629	
Site: Fred's Auto Junkyard		
Camera: Make Pentax	SN 4759340 (EPA Decal 897603)	
Lens Type 50 mm	SN 367638	
	Photographer: J. McCall Date: 8/26/93	
	Time: 1138 Frame No.: 4	
	Comments*: View of area in which mobile automobile	
	crusher is used.	
	*Comments to include location.	



ecole PHC	ogy and environment, inc. OTOGRAPHIC RECORD
Client: EPA Region III	E & E Job No.: ZE5629
Site: Fred's Auto Junkyard	
Camera: Make Pentax	SN 4759340 (EPA Decal 897603)
Lens Type 50 mm	SN 367638
	Photographer: J. McCall Date: 8/26/93
	Time: 1138 Frame No.: 7
	Comments*: View of area in which automobile crusher is
	used.



eco PH	logy and environment, inc. IOTOGRAPHIC RECORD
Client: EPA Region III	E & E Job No.: ZE5629
Site: Fred's Auto Junkyard	
Camera: Make Pentax	SN 4759340 (EPA Decal 897603)
Lens Type 50 mm	SN 367638
	Photographer: J. McCall Date: 8/26/93
	Time: 1148 Frame No.: 14
	Comments*: Two metal hoppers located on the east side of
	the site.
	*Comments to include location.



	ology and environment, inc. HOTOGRAPHIC RECORD
Client: EPA Region III	E & E Job No.: ZE5629
Site: Fred's Auto Junkyard	
Camera: Make Pentax	SN 4759340 (EPA Decal 897603)
Lens Type 50 mm	SN 367638
	Photographer: J. McCall Date: 8/26/93
	Time: 1153 Frame No.: 16
	Comments*: Several drums and empty tanks located south
	of the garage. Used automotive oil filters are burned in
	these drums.
	*Comments to include location.






	ecology and environment, inc. PHOTOGRAPHIC RECORD
Client: EPA Region III	E & E Job No.: ZE5629
Site: Fred's Auto Junkyard	
Camera: Make Pentax	SN 4759340 (EPA Decal 897603)
Lens Type 50 mm	SN 367638
	Photographer: J. McCall Date: 8/26/93
	Time: 1154 Frame No.: 17
	Comments*: Drums, heating oil tank, and buckets on east
	side of the garage. Drums are used to hold waste automotive
	motor oil or scraps. Buckets are used to collect rain water.
	*Comments to include location.





ecology and environment, inc. PHOTOGRAPHIC RECORD				
Client: EPA R	egion III	E & E Job No.: ZE5629		
Site: Fred's	auto Junkyard			
Camera: Make	Pentax	SN 4759340 (EPA Decal 897603)		
Lens Ty	pe 50 mm	SN 367638		
		Photographer: J. McCall Date: 8/26/93		
		Time: 1200 Frame No.: 18		
		Comments*: View of parts cleaner located in garage (som		
		corrosion on outside). The unit is no longer active.		



APPENDIX B

EPA FORM 2070-12

POTENTIAL HAZARDOUS WASTE SITE PRELIMINARY ASSESSMENT		I. IDENTIFICATION			
PART 1 - SITE LOCATION AND ASSESSMENT	01 State PA-3017	02 Site Number PAD987378213			
II. SITE NAME AND LOCATION					
01 Site Name (legal, common, or descriptive name of site) 02 Street, Route No., or specific location identifier 2650 Egypt Road					·
03 City	04 State	05 Zip Code	06 County	07 County	08 Cong.
Lower Providence Township	PA	19403	Montgomery	Code 091	Dist. 17
09 Coordinates Latitude Longitude 40 ° 07 2 45 " Longitude 75 ° 24 2 45 "					
10 Directions to Site (starting from nearest public road) 422 to Trooper Road exit. Take Trooper Road 1.3 miles to Egypt Road, turn left, go 0.3 mile to site.					
III. RESPONSIBLE PARTIES					
01 Owner (if known) Neilson Real Estate	02 Street (Business, mailing, residential) 2620 Egypt Road				
03 City Norristown	04 State PA	06 Zip Code 19403	08 Telephone (215) 631-		
07 Operator (if known and different from owner) Fred Melchiorre	08 Street (Business 2650 Egypt Ros	s, mailing, residential) ad			
09 City Norristowa	10 State PA	11 Zip Code 19403	12 Telephone (215) 666		•
13 Type of Ownership (check one) [X] A. Private [] B. Federal [] C. State [.] D. County [] E. Municipal (agency name) [] F. Other [] G. Unknown (specify)					
14 Owner/Operator Notification on File (Check all that apply) [] A. RCRA 3001 Date Received / / [] B. Uncontrolled Waste Site (CERCLA 103c) Date Received / / [X] C. None Month Day Year.					
IV. CHARACTERIZATION OF POTENTIAL HAZARD					
01 On-Site Inspection By (check all that apply) [X] Yes. Date 8/26/93 [] A. EPA [X] B. EPA Contractor [] C. State [] D. Other Contractor [] No Month Day Year [] E. Local Health Official [] F. Other					
(specify) Contractor Name(s) Ecology and Environment, Inc., (E & E)					
02 Site Status (check one) [X] A. Active [] B. Inactive [] C. Unknown	03 Years of Opera	tion 1955 Beginning Year		[] Unkno	wn
04 Description of Substances Possibly Present Known or Alleged Trichloroethene (TCE) has been detected in nearby homewells. Used motor oil is stored and burned on site.					
05 Description of Potential Hazard to Environment and/or Population	,	नार्वहरूत । १५०			
V. PRIORITY ASSESSMENT			· · · · · · · · · · · · · · · · · · ·		
01 Priority for Inspection (Check one. If high or medium is checked, complete Par [] A. High [] B. Medium [] C. L (Inspection required promptly). (Inspection required) (Ins		[] D. None	1000	Conditions and Incide	
VI. INFORMATION AVAILABLE FROM					
01 Contact 02 Of (Agency/Organization) 03 Telephone Number Ecology and Environment, Inc.					
04 Person Responsible for Assessment 05 Agency Michael Giuranna EPA	06 Organization	07 Telephone Nu (215) 597-3165		08 Date /	/ Year

	HAZARDOUS WAS	TE SITE	i. identification	The second of th	
PART	2 - WASTE INFORMATION	<u>'</u> r	01 State PA-3017	02 Site Number PAD987378213	* ************************************
II. WASTE STATES, QUAN	TITIES, AND CHARACTERIST	ncs			
01 Physical States (check all to [] A. Solid [] B. Powder, Fines [] C. Sludge [] D. Other	hat apply) [] E. Shurry [X] F. Liquid	02 Waste Quantity at waste quantities must large Tons Cubic Yards Unl	ne independent)	[] B. Corrosive [] C. Radioactive [] D. Persistent [] E. Soluble	
III. WASTE TYPE				NAME OF THE PARTY	
Category	Substance Name	01 Gross Amount	02 Unit of Measure	03 Comments	(A) (A) (A)
SLU	Studge			LINE LOS	
OLW	Oily waste	70	Gallons	Used motor oil stored on a	ite.
SOL	Solvents	Unknown	,	TCE detected in area hom	ewells and community wells.
PSD	Pesticides			P	
ooc	Other organic chemicals	14 4			The state of the s
IOC	Inorganic chemicals				
ACD	Acids	1			
BAS	Bases	, 1	,		
MES	Heavy metals				
IV. HAZARDOUS SUBSTA	NCES (see Appendix for most fro	equently cited CAS Num	bers)		
01 Сатедоту	02 Substance Name	03 CAS Number	04 Storage/Disposal Method	05 Concentration	06 Measure of Concentration
SOL	TCE	79-01-6	Detected in area homewells and community wells	up to 399	ppb
		* *	,1 s.7		
V. FEEDSTOCKS (see App	endix for CAS Numbers)				
Category	01 Feedstock Name	02 CAS Number	Category	01 Feedstock Name	02 CAS Number
FDS	Not Applicable	1 25 2	FDS		
FDS			FDS		And the second second
FDS			FDS		
FDS			FDS		
	IATION (cite specific references,			j. 18 1 1 .	

POTENTIAL HAZARDOUS WASTE SITE PRELIMINARY ASSESSMENT	I. IDENTIFICATI	ON		
PART 3 - DESCRIPTION OF HAZARDOUS CONDITIONS AND INCIDENTS	01 State PA-3017	02 Site Number PAD98737821	13	
II. HAZARDOUS CONDITIONS AND INCIDENTS	•. •. •.	1 1	, Alexander (1)	
01 [X] A. Groundwater Contamination 02 [X] Observ 03 Population Potentially Affected 29,919 04 Narrative D	ved (date ~1980 Description:)	[] Potential	[] Alleged
TCE was detected in area homewells and municipal wells. The municipal water supp has not been positively identified:	ply is treated; area homew	ell owners have obtaine	ed alternate supplies.	The source of TCE
01 [] B. Surface Water Contamination 02 [] Observ 03 Population Potentially Affected 04 Narrative D	ved (date) Description:		[] Potential	[] Alleged
				1
01 [] C. Contamination of Air 02 [] Observ 03 Population Potentially Affected 04 Narrative D		ý.	[] Potential	[] Alleged
				<u>.</u>
01 [] D. Fire/Explosive Conditions 02 [] Observ 03 Population Potentially Affected 04 Narrative D			[] Potential	[] Alleged
01 [] E. Direct Contact 03 Population Potentially Affected 04 Narrative D			[] Potential	[] Alleged
01 [] F. Contamination of Soil 02 [] Observ 03 Area Potentially Affected 04 Narrative D	rved (date) Description:	on Marine Control	[] Potential	[] Alleged
W Alex Potentially Affector		·		
01 [] G. Drinking Water Contamination 02 [] Observ 03 Population Potentially Affected 04 Narrative E			[] Potential	[] Alleged
	£.	, s	<u> </u>	· ·
01 [X] H. Worker Exposure/Injury 02 [] Observ 03 Workers Potentially Affected 1 04 Narrative E		7 (1) (1) (1) (1) (1) (1) (1) (1	[X] Potential	[] Alleged
Burning of waste motor oil and automotive oil filters on site.				
01 [] I. Population Exposure/Injury 02 [] Obser 03 Population Potentially Affected 04 Narrative I			[] Potential	[] Alleged
the control of the co				· . · · · · · · · · · · · · · · · · · ·

POTENTIAL HAZARDOU PRELIMINARY ASSES		I. IDENTIFICATIO	IN State of the st	
PART 3 - DESCRIPTION OF CONDITIONS AND INC		01 State PA-3017	02 Site Number PAD987378213	
II. HAZARDOUS CONDITIONS AND INCIDENT	S (Cont.)		AND THE RESERVE OF THE PERSON	
01 [] J. Damage to Flora 04 Narrative Description:	02 [] Observed ((date	[] Potential [] Alleged	
01 [] K. Damage to Fauna 04 Narrative Description:	02 [] Observed ((date	[] -Potential [] Alleged	
			A State of the sta	١,
01 [] L. Contamination of Food Chain 04 Narrative Description:	02 [] Observed ((date	[] Potential [] Alleged	, .
				2
01 [] M. Unstable Containment of Wastes (spills/runoff/standing liquids, leaking drums) 03 Population Potentially Affected: 04 Narrative Description:	O2 [] Observed ((date	[] Potential [] Alleged	
01 [] N. Damage to Off-site Property 04 Narrative Description:	02 [] Observed	(date)	[] Potential [] Alleged	
01 [] O. Contamination of Sewers, Storm Drains 04 Narrative Description:	o, WWTPs 02 [] Observed	(date	[] Potential [] Alleged	
01 [] P. Illegal/Unauthorized Dumping 04 Narrative Description:	02 [] Observed	(date	[] Potential [] Alleged	
		. 1		\$ \$
05 Description of Any Other Known, Potential, or A	Alleged Hazards			
III. TOTAL POPULATION POTENTIALLY AFFI	ECTED <u>29,919</u>	7 V	en et al. All and all all all all all all all all all al	
IV. COMMENTS		——————————————————————————————————————		
		positively identified. Po	opulation potentially affected includes all persons within 4 n	niles

EPA FORM 2070-12(7-81) 02:ZE5629_D4376_PA-11/10/93-D1

U.S. EPA Region III, file information.

APPENDIX C

ANALYTICAL RESULTS FOR AREA HOMEWELLS

	Well Location/ sampling date	TCE	`	TCA		1,1-DC	E	TR 1,	2-DCE	1,1,-(DCA	PCE	Maria .	CHLORO	FORM	1,2-DC	A	Quant i ta	tion Limit
		in	out	in	out :	in	out	in	out	in	out	in	out	in	out	in	out		
	· 9/15/84	<1.0	1	NR	٠	NR	8	. N	R	NR	; ;:1	NR		NR	M.	NR		1.0	
	6/04/87	NS		NS		NS) N		NS		NS		NS		NS			• •
	10/14/87	NS	- 24	NS		NS	22 74 E	ÀÑ	- *	NS		NS		NS		NS	, al " " "	10.3	•
	1/13/88	NS :		NS	-	NS		N		NS		NS		NS		NS	e great		
	7/18/88	NS		NS NS		NS NS	2° '''	N		NS NS	¥ .	NS NS		NS.		NS NS	7 1	,,,	
	11/08/88 3/03/89	NS NS	. · · · · · · · · · · · · · · · · · · ·	NS NS		NS		. N		NS-	. 100	NS	. 13	NS	•	NS			٠
	3703707	~~				, ,									,	Υ.	· 4		
					. `			. 1. 1), · · · ·	, and a		1,30	- 3	, · ·	¥
	.9/15/84	<1.0		- NR		NR		Ň		NR		NR		NR		NR		1.0	
	6/04/87	NS	~	NS		NS			S S	NS NS	٠.	NS NS		NS NS		NS NS	10, 20		$V_{4,1}$
• '	10/14/87	NS NS		NS NS	-; \	NS NS		, N		NS NS		NS		NS	٠	NS	u di ju	Ì	<u>,</u> *
	1/13/88 7/18/88	NS -		NS		NS.	**		S	NS		NS	_	NS		:NS			r
	11/08/88	NS	.	NS		NS	,		S	/ NS		NS		MS		NS		, ·	
	3/03/89	NS	i	NS		NS	•	/ N	S _	.NS	- 1	NS		NS	٠.	: NS	<u>,</u> ,	A 5	e ja saita a
								1.5				٠.	٠,	•	4	**		,	
	0/35/9/	1.3	<1.0	NR		. NR		۱ .	R	NR	c.	NR		NR		NR	٠	1.0	
	9/15/84 6/04/87	ND	ND		4.8	ND	ND		D ND	ND	ND	ND		20.0		ND	ND	1.0	
	10/14/87	<1.0	, ,	6:0		<1.0		N	D ···	<1.0		ND		40.0		ND	**.	1.0	:
	1/13/88	<1.0	٠.	12.0		1.0			D :	1.0		1.0		37.0		ND		1.0 1.0	
	7/19/88	. ND		12.0	14	, ND ND		•	D D	ND ND	· .	ND ND		39.0 26.0		ND ND		1.0	
	11/08/88	ND NS	•	2.3 NS	- 1	NS			S.	NS		NS		NS		NS	•	1	
	3/03/89	N3			*		:	i "	-1	1					•	l	٠		•
		٠.,		·						i					•				
	9/15/84	1.4		NR		NR	٠ ،		IR ·	NR.	410	NR		NR 6.7		NR ND	ND .	1.0	
	6/04/87	<1.0	1.3		ND	4.2 2.0	ND		ID 2.1	1.5	ND	ND ND		7.0		ND	MU	1.0	
,	10/14/87 1/13/88	<1.0 1.0		45.0 35.0		3.0		3.		1.0		<1.0		13.0		ND		1.0	
	7/19/88	ND		30.0		ND		•	ID.	ND		ND		9.9		ND		1.0	\$
	11/08/88	ND	ND 3	22.0	21.0	1.2	31.0		D . ND	ND	ND	ND		7.8		ND	MD	1.0	•
	3/03/89	ot a NS		NS		.NS			is į	, NS	-	NS	;	NS.		NS.		ļ.	
			٠.		•	170		y o	37	1 50						· .	, ,	. "	
٠,	0/15/8/	<1.0		NR	. · .	NR		١,	IR.	NR	". ·	NR	1	NR		NR	L.,	1.0	λ,
	9/15/84 6/04/87	<1.0	ND	12.0	· ND	ND			ID ND	ND	ND	ND		15.0	ND	NÒ	ND	1.0	
	10/16/87	<1.0		26.0	·	<1.0			ID .	<1.0		ND		35.0		ND		1.0	
•	1/13/88	1.0		24.0		1.0	_	<1.	* *	2.0		4.0		81.0		ND		1.0) () ablas
	1 / 1 / / 00	, ND		57.0		ND			ID.	2.5		ND NS		63.0 NS		ND NS	-y. 7.	1.0; 50	0.0 chlor.
٠.	ω _{11/08/88}	NS	,	NS NS	·.	NS NS	1.12		IS IS	NS NS	• .•	NS		NS		NS NS		· ·	
	3/03/89	NS		1 мэ	, -	1 42	1.1	•	••	, H3		, ,,,		1 ,70			* *	•	

 \sim တ်

in, out - influent and effluent samples
<1.0, BMDL, J - Present below quantitation limit.
The quantitation limit was raised for diluted samples. NR - Not requested.

NS - Not sampled.

⁽F) Filter installed by EMS Resource Group for CSG-

⁽f) - filter installed by homeowner ND - Not detected at quantitation limit.

SUMMARY OF RESIDENTIAL GROUNDWATER QUALITY ANALYSES, COMMODORE SITE, PA 1984-1989 [Concentrations in parts per billion.]

· · · · · · · · · · · · · · · · · · ·						i.		٠.				·							
Well Location/ sampling date	TCE		TCA	*	1, 1-D0	Œ	TR 1,2-	DCE	÷ 1,1-0	CA	PCE	·	CHLORO	FORM	1,2-DC/	V 2.2	Quant i	tation Limi	įţ
	iń	out	in in i	out:	in	out	in	out	in	out	in	out	l in	out	in	out			
			T "		ļ:		Î .		i			•				out	1	5	
9/15/84	1.6	• • •	NR.		NR.	-	NR NR	· ·:	NR	1.	. NR		NR.		NR		1.0		
6/04/87	ND	ND	13.0	2.9	<1.0	ND	ND.	ND	ND .	ND	ND	- ND	26.0	2.0	ND	ND	1.0	J. 74.	
10/14/87	<1.0		22.0		<1.0		, ND	, .	1.1.0	•	i .		25.0		ND	NO	1.0	,	
1/13/88	<1.0		<1.0		<1.0.		ND		<1.0		<1.0		2.0		ND ND		1.0		
7/19/88	ND		42.0		ND.	-	ND ND		1.9	<i>ij</i>	ND	,	91.0		ND			20.0 chlor.	
11/08/88	ND.	ND	160.0	ND	ND	· ND	ND.	: ND	ND	ND	ND	ND	450.0	24.0	ND	ND	10.0	. 10.0 , 6117, 01.0	
3/03/89	NS		NS.		NS		NS	• •	į NS		NS		l NS		NŜ.	ND.	10.0	-	
<u> </u>					· · · · ·	.4	İ		i •		i			ľ	, . ,		i		
].	"			İ		i		i .		ì	ľ			i		:
9/15/84	6.1		NR		NR		NR NR		NR		NR		. NR	ľ	NR		1.0		
6/04/87	1.6	MD	1.6	<1.0	ND	ND	ND	ND	j 1.7.	ND	i ND	ND	7.4	ND	ND	MD	1.0		
10/14/87	1.0		1.0	i	<1.0		, MD		<1.0		1.0		5.0		ND.	no.	1.0		'
1/13/88	2.0	٠. ا	2.0	i	<1.0		<1.0		2.0	. '	1.0		12.0		ND ND		1.0		
7/19/88	.75J		2.6	. i	ND	i	ND		2.9	٠,	ND		19.0		ND.		1.0		
11/10/88	1.3	1.1.	1.5	່ 1.3	. ND	ND	1.9	ND	ND	ND	ND:	. ND	15.0	14 0	ND	ND			
3/03/89	NS	i	NS	i	NS	-7	NS		NS		l NS	, AU	NS	14.0	NS NS	NU	1.0		٠
,				i		-					"3		#3 	!	М2		į.		
	-	·		i									·	!					
9/15/84	<1.0	i	NR	i	NR	. i	NR		NR NR		NR		NR	!					
6/04/87	NS.	•	NS.	i		i	NS.		NS NS		NS		I NK	· !	NR		1.0		•
10/14/87	NS	i	NS	4	NS NS	·	. · NS		l NS		i MS	'	NS NS	· !	NS*		!		•
1/13/88	NS.	· i	NS		: NS	i	NS:		NS .		NS		NS NS		NS		ļ		•-
7/18/88	NS	i	NS		· NS	i	NS		l NS	•		ļ		!	NS		1	•	•
11/08/88	NS	i	NS	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	NS	ľ	NS		NS	1.0	NS	7 - J-1	NS NS	!	NS	, ,	ī.		•
3/03/89	NS	i	NS	i	NS	ı i	NS		NS	,	NS NS		NS	!	NS	. [12	*. • *	
	. '	i		i	, 45	ľ	H.J.		113	ŀ	H 3	- 1	N2	!	NS		er i		
		i		- 1	. · · · · ·	· ¦	• ,		Jāras Norte			· !	3	. !	te.		1	``	. :
9/15/84	<1.0	`. I	: NR	i i	NR	1	NR.		NR		5 Alm .	. :	3 · · ·	. !		ļ			
6/04/87	ND	ND	1.6	1.6	ND	ND ∴Î	ND.	ND I	i ND		NR NR		NR	, !	NR	!	1.0		
10/14/87	<1.0		<1.0	1.5	<1.0	וי טא		י טויי		∵ND	ND	ND.	3.9	, ND	ND	ND .	1.0		
224 3/88	1.0	- 1	<1.0	ļ	<1.0	. !	ND ND		<1.0		ND	٠ !	1.0	ж.	ND	-	1.0		
7(18/88	NS	. !	NS	. !			ND		<1.0	ļ	<1.0	<u> </u>	3.0	- 1	ND	_	1.0	_	
14/98/88	NS	ł		ļ	NS		NS	• •	NS	ļ	NS	- 1	NS.		NS	· [
7403/80	NS NS	.	NS	ļ.	NS		NS		NS	ļ	NS]	NS	्री'	NS	j	• • • • • • •		
21 93/89	¥2	-, I	NS	.1	NS		NS	/-	NS		NS .		NS	. 1.	NS				
			, ,				<u>r</u> .			, •			. :		5 - A.				*

Notes: , N

Ó

in, out dinfluent and effluent samples ...

<1.0, BMDL, J - Present below quantitation limit.

The quantitation limit was raised for diluted samples.

NR - Not requested.

NS - Not sampled.

(F) Filter installed by EMS Resource Group for CSG

(f) - filter installed by homeowner

Well Location/ sampling date	TCE		TCA	1,1-DCE	TR 1,2-DCE	1,1-DCA	PCE	CHLOROFORM	1,2-DCA	Quantitation Limit
Sampting date	in	out	l in out	in out	in out	l in out	in out	in out	in out	- No. 1
•			-5, 11 g			18.		1 1 1 1 1 1		· 、
9/15/84	<1.0		NR	NR	NR .	NR	NR	NR	NR	1.0
3/03/86	ND		ND	NR 🕞	ND	NR	NR	NR ×	NR a	1.0
6/23/86	ND		ND.	NR	ND	NR .	NR "	NR	NR .	5.0
10/23/86	ND		ND	ND	ND 7	ND	ND	ND.	ND	1.0
6/04/87	ND	ND	ND ND	<1.0 NO	ND ND	ND ND	ND ND	4.6 2.6	ND ND	1.0
10/14/87	ND		<1.0	ND 4	ND	ND	ND	2.0	ND A	1.0
1/13/88	<1.0	4,	<1.0	<1.0	ND ND	<1.0	<1.0	3.0	ND .	1.0
7/18/88	NS	- 1971)	NS .	NS Sec	NS	NS	NS ,	NS NS	NS NS	
11/08/88	· NS	,	NS at	NS	NS	NS .	NS NS	NS NS	NS 🤇	
3/03/89	NS	:	NS ME	NS *	NS	NS .	NS .	NS	NS V	
	1.12	^i,				1 3 %	1 特集的	1	11 2	
	· . ,	· ·								
9/15/84	<1.0	*	NR	NR	NR *	NR .	NR	™ NR	NR.	1.0
6/04/87	NS	×	NS .	NS	NS	l NS	NS	NS	NS	
10/14/87	NS	. <i></i>	NS S	"Į. ⇔NS	, NS	NS	NS S	NS .	NS	
1/13/88	NS		NS	NS	NS	NS	NS	l NS	NS NS	1 P 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
7/18/88	NS		NS .	NS *	NS	NS	NS NS	NS NS	NS NS	
11/08/88	, NS		NS	NS NS	NS	NS	NS NS	NS NS	NS	**
3/03/89	NS		NS.	NS NS	NS	NS	NS	M3	1 13	2.7 c
	i i v	A					1			1 1
1.5		4	19	9		1	NR	NR	₩NR	1.0
9/15/84	<1.0	·	NR	NR NR	NR	NR ND	ND ND	3.9	ND ND	1.0
6/04/87	ND	<1.0	1.3 ND	ND 1.0	ND ND	<1.0	ND.	2.0	/ ND	1.0
10/14/87	ND 1	* ****	<1.0	<1.0	ND	<1.0	<1.0	3.0	ND	1.0
1/13/88	ND	, ,	<1.0	NS	NS	NS NS	NS	NS	NS A	4
7/18/88	NS	. :	NS	NS NS	. NS	NS NS	NS	NS	NS	
11/08/88	NS		NS NS	NS	NS	NS	NS	- , NS	NS	
3/03/89	NS		МЭ 👙	1 "3	1 3 43				** *	
	2.3			11 V	1 1.			1	1	1
0.45.494	<1.0		NR NR	NR	NR .	NR	NR NR	NR	NR	1.0
<u>19/15/84</u>		, ,	NS	NS	NS	NS 2	NS	NS	. NS	
-6/04/87 -10/14/87	NS NS		NS	NS NS	NS	NS	NS	NS'	NS	1.345
14/8/ 13/88	NS	. [-1	NS S	NS	NS	NS	NS	NS	NS	A Comment of the Comm
/18/88	NS	3	NS NS	NS	NS NS	NS	. NS	NS	NS	
G9/08/88	NS NS	·	NS	NS :	NS	NS	NS	NS	NS	
1 3/03/89	NS		NS	NS	NS	NS	NS	NS	NS	
(A)			,	•	•		· · · · · · · · · · · · · · · · · · ·	<u> </u>		

Nobes:

in, out - influent and effluent samples

The quantitation limit was raised for diluted samples.

- (F) Filter installed by EMS Resource Group for CSG
- (f) filter installed by homeowner
- ND Not detected at quantitation limit.

<1.0, BMDL, J - Present below quantitation limit.

NS Not sampled.

SUMMARY OF RESIDENTIAL GROUNDWATER QUALITY ANALYSES, COMMODORE SITE, PA. 1984-1989 [Concentrations in parts per billion.]

	<u> </u>	. 4	to the state of	14	<u> 18 agos - 18 a</u>		ger g . Si.			
Well Location/	TCE		TCA	1,1-DCE	TR 1,2-DCE	1,1-DCA	PCE	CHLOROFORM	1,2-DCA	Quantitation Limit
sampling date			l in out	1 22 22		-	- 10 ha		· · ·	
	in.	out	in out	in out	in out	in out	in out	in out∜	in 🕜 out	
9/15/84	<1.0	-	NR	NR	NR.	NR				1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -
3/03/86	ND		ND	NR NR	ND	NR .	NR NR	NR NA	NR .	1.0
6/23/86	ND:		ND.	NR	ND	NR NR	NR	NR NR	NR NR	1.0
10/23/86	ND .		ND ₅	ND	. ND	ND	ND	ND	ND ND	5.0 1.0
6/04/87	ND		NĎ	ND	ND	ND	ND:	2.4	ND	1.0
10/14/87	ND		ND	ND	ND	ND	ND	1.0	ND .	1.0
1/13/88	<1.0		14.0	1.0	ND .	1.0	1.0	39.0	ND	1.0
7/18/88	NS		NS "	NS	NS	NS.	NS	NS	NS	
11/08/88	NS		NS	NS	NS	NS	NS	NS	NS *	
3/03/89	NS.		NS	NS	NS.	NS .	NS	NS	NS	
* .×* · ·	. ,		200				1			4 14 14 14 14 14 14 14 14 14 14 14 14 14
9/15/84	8.0	· AGE	WR	A NR				2		
3/03/86	ND .	44.	ND	NR NR	NR ND	NR NR	NR NO	NR	NR	1.0
6/23/86			NR	NR.	NR	NR NR	NR NR	NR NR	NR NR	1.0
6/04/87	<1.0	ND	2.9 2.4	ND ND	1.6 ND	ND ND	ND ND	ND ND	ND ND	5.0 1.0
10/14/87	2.0		<1.0	ND	<1.0	ND ND	ND ND	<1.0	ND ND	1.0
1/13/88	NS		WS"	NS	A NS	NS	NS	NS	MC	
7/18/88	NS	, '	NS	NS	ins	NS	NS	. NS	NS NS	
11/08/88	NS	12.1	NS TO THE	; NS	NS .	NS	NS	NS"	NS	78 H
3/06/89	ND ·	1.5	ND	ND	ND	ND	ND ND	ND .	· ND	1.0
Marine State Control				200	Å.		13-			
9/15/84	NS		NS NS			NS *		10.00	**	
6/04/87	2.0	MD	<1.0 ND	NS ND ND	NS ND	NS ND ND	NS ND <1.0	NS	NS	
10/14/87	NC .	7	NS	NS NS	NS NS	NSC.	ND < 1.U	ND ND NS	ND ND NS	1.0
1/13/88	NS		NS	NS	NS	NS:	1 40 1	NS NS	NS.	
7/18/88	NS	1	MS	NS		NS:	NS A	NS NS	NS NS	
11/08/88	NS		NS	NS	NS	NS	NS	NS	NS	
3/06/89	1.3		ND	ND	3.1	ND	ND	ND	ND	1.0
		i	4		1.7	1			1.15	
0.45.04		**			· •					
9/15/84 6/04/87	4.6	ND	NR*	NR	NR	NR .	NR I	NR -	NR	1.0
10/14/87 11/13/88	1.3 NS	NU	ND <1.0	ND ND NS	2.3 ND	ND ND	AND ND	ND ND	ND ND	1, 1.0 N
/13/88	NS		NS	NS NS	NS	NS	NS	NS 8	NS 🔆	
7/18/88	NS		NS	NS NS	NS NS	NS NS	NS I	NS	NS	
C+9/08/88	NS.	ĺ	NS	NS NS	NS NS	NS	NS NS	NS NS	NS	
3 /07/89	2.0	i	14.0	ND	ND	ND ND	ND ND	ND ND	NS ND	10
		<u>'</u>				inge ry Tanang Tanang	• • • • • • • • • • • • • • • • • • •	,		or T.U. Alexander (1997) Since the State of Asian
										4

Vates:

in, out - influent and effluent samples

<1.0, BHDL, J - Present below quantitation limit.

VS - Not sampled

(F) - Filter installed by EMS Resource Group for CSG; *=absent as of March 1989

The quantitation limit was raised for diluted samples.

NR - Not requested.

⁽f) - filter installed by homeowner; f1-softener

 Well Location/	TCE		TCA		1,1	-DCE	TR 1,2-1	DCE	1,1-0	CA	PCE	CHLOROFORM	1,2-DCA	Quantitation Limit
9/15/84 6/04/87 10/14/87 1/13/88 7/21/88 11/10/88 3/07/89	8.7 ND NS NS ND ND	out ND	NR 4.6 NS NS ND ND	ND		NR ND ND NS NS ND ND ND	NR 2.4 MS NS ND ND ND	out ND	IN NR ND NS NS ND ND	ND	IN OUT NR ND ND NS NS ND ND ND	NR 1.9 3.3 NS NS NS ND ND ND	IN OUT NR ND NS NS NS ND ND ND ND	1.0 1.0 1.0 1.0 1.0
9/15/84 6/04/87 10/14/87 1/13/88 7/21/88 11/08/88 3/08/89	3.2 NS NS NS 3.4 4.5	<1.0	NR NS NS ND ND ND			NR NS NS NS ND ND	NR NS NS 9:9 6.3 6.6		NR NS NS NS ND ND ND		NR NS NS NS ND ND	NR NS NS NS ND ND	NR NS NS NS NS ND ND	1.0 1.0 1.0
9/15/84 6/04/87 10/14/87 1/13/88 7/18/88 11/08/88 3/08/89	34.0 <1.0 NS NS NS NS 2.3	<1.0 ND	NR 2.9 NS NS NS NS	2.8	Į.	NR ND ND NS NS NS NS	NR ND MS MS NS NS	ND :	NR ND NS NS NS NS	ND	NR ND ND NS NS NS NS	NR ND 1.1 NS NS NS NS	NR ND ND NS NS NS NS	1.0
9/15/84 6/04/87 10/14/87 1/13/88 7/18/88 11/08/88 3/07/89	31.0 ND NS NS NS		NR ND NS NS NS NS	•	, ,	NR ND NS NS NS NS	NR 1.1 NS NS NS NS		NR ND NS NS NS NS		NR ND NS NS NS NS	NR ND NS NS NS NS	NR ND NS NS NS NS	1.0
9/15/84 3/03/86 3/03/86 -10/23/86 -10/23/86 6/04/87 -113/88 -113/88 -11/08/88 -1/08/88	8.9 6.0 ND 1.6 1.0 1.0 NS	ND	NR ND <5.0 ND <1.0 <1.0 <1.0 NS NS	: .		NR NR NR ND ND ND ND ND ND NS NS	NR * ND <5,0' ND 1.9 1.0 1.0 NS NS		NR NR NR ND ND ND ND NS NS	ND	MR NR NR ND ND ND ND ND NS NS	NR NR NR ND	NR NR NR MD MD ND ND ND ND NS NS	1.0 1.0 5.0 1.0 1.0 1.0

Moses:

in, out - influent and effluent samples.
<1.0, BMDL, J - Present below quantitation limit.
The quantitation limit was raised for diluted samples. NR - Not requested.

NS Notesampled.

(F) - Filter installed by EMS Resource Group for CSG

(f) - filter installed by homeowner

ND - Not detected at quantitation limit.

1	_	3 3-2				<u> </u>			· ,		•*
10			TCE	TCA	1,1-DCE	TR 1,2 DCE	1,1-DCA	PCE	CHLOROFORM	1,2-DCA	Quantitation Limit
9/15/84 <1.0 NR NR NR NR NR NR NR NR NR NR NR NR NR							1	1 :	1 2	1 7	
9/15/84 <1.0 NR NR NR NR NR NR NR NR NR NR NR NR NR			in out	•	I in out		in out			in out	!
6/04/87 NS NS NS NS NS NS NS NS NS NS NS NS NS		0.115 (8/		1.					,		1
10/14/87 MS MS MS MS MS MS MS MS MS MS MS MS MS							•	•			1.0
1/13/88							₹	•	•	,	. .
7/18/88					•		**		T.		ľ
11/08/88						•		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		•	17
3/03/89 NS				3			1.				
9/15/84 <1.0 MR MR NR MR MR MR MR MR 1.0 MS 1.0 MS MS MS MS MS MS MS MS MS MS MS MS MS				1 .				1.	1.4		}
9/15/84 <1.0 NR NR NR NR NR NR NR NR NR NR NR NR NR		•	MS.	45	"3	, 43,	Ha .	, ns	, M3	H3	
6/04/87 NS NS NS NS NS NS NS NS NS NS NS NS NS		7. : <u>*</u> :	2.0					1. 1.	*	i .	
6/04/87 NS NS NS NS NS NS NS NS NS NS NS NS NS		0/15/0/	-10	NO .	ND.	ND .	ND.	⁷ ND	l up	MD	1 1 0
10/14/87 NS	,			•		1	,	1	!		
1/13/88				The second secon			1		P 1		
7/18/88 NS NS NS NS NS NS NS NS NS NS NS NS NS	•						•	•	1		
11/08/88	.•						F	1			
3/03/89 NS NS NS NS NS NS NS NS NS NS NS NS NS											
9/15/84 <1.0 NR NR NR NR NR NR NR NR NR 1.0 3/03/86 ND ND ND NR ND NR NR NR NR NR NR 1.0 6/23/86 ND ND ND ND ND ND ND ND ND ND ND ND ND									•		1 5
9/15/84 <1.0 NR NR NR NR NR NR NR NR 1.0 3/03/86 ND ND NR ND NR ND NR NR NR NR NR NR NR 1.0 6/23/86 ND ND ND NR ND NR NR NR NR NR NR 1.0 1.0 10/23/86 ND ND ND ND ND ND ND ND ND ND ND ND ND	•		МЭ .	, ns	#3	"3	H3	"3	H 43	, "3	1
9/15/84 <1.0 NR NR NR NR NR NR NR NR 1.0 3/03/86 ND ND NR ND NR NR NR NR NR NR 1.0 6/23/86 ND ND ND NR NR NR NR NR NR NR NR 1.0 10/23/86 ND 1.0 1.0 1.0 ND ND ND ND ND ND ND 1.0 1.0 1.0 1.0 1.0 ND ND ND ND ND ND ND ND ND 1.0 1.0 1.0 1.0 1.0 ND ND ND ND ND ND ND ND ND ND							57.		}	,	
3/03/86 ND ND ND NR ND NR NR NR NR NR 1.0 6/23/86 ND ND ND ND ND ND ND ND ND ND ND ND ND		0/15/8/	.i. n	. NO	MD ·	ND	ND		No.	, MD	1.0
6/23/86 ND ND ND ND ND ND ND ND ND ND ND ND ND				,	•	,					1
10/23/86 ND ND ND ND ND ND ND ND ND ND ND ND 1.0 6/04/87 ND ND <1.0 ND ND ND ND ND ND ND 1.0 1/13/88 <1.0 <1.0 ND ND ND ND ND ND ND ND ND 1.0 7/18/88 NS NS NS NS NS NS NS NS NS NS NS NS NS				II.		•		•			7.
6/04/87 ND ND ND ND ND ND ND ND ND 1.0 10/14/87 ND <1.0 ND ND ND ND ND ND 1.0 1/13/88 <1.0 <1.0 ND ND ND ND ND ND ND ND ND ND ND ND ND				1.	•	•		1			•
10/14/87 ND <1.0 ND ND ND ND ND ND 1.0 1/13/88 <1.0 <1.0 ND ND ND ND ND ND ND 1.0 7/18/88 NS NS NS NS NS NS NS NS NS NS NS NS NS	- · · ·			•	,			To a			
1/13/88 <1.0 <1.0 ND ND ND ND ND 1.0 7/18/88 NS NS NS NS NS NS NS NS NS NS NS NS NS						1 4	4		X		
7/18/88 NS NS NS NS NS NS NS NS NS NS NS NS NS									1		
11/08/88 NS NS NS NS NS NS NS NS NS NS NS NS NS				1.77		7.7		· U.			
3/03/89 NS NS NS NS NS										Pi .	
		3/03/80				•		P 1.1		** ** ***	**
		3,03,0,	#3	""			<u> </u>		1 "		i
										1	
9/15/84 <1:0 NR NR NR NR NR NR 1.0		9/15/84	<1:0	NR S	NR	NR .	NR	NR	NR	NR	1.0
6/04/87 NS NS NS NS NS NS					1				•	1	
10/14/87 NS NS NS NS NS NS		_10/14/87			•	•	•	1			i
13/88 NS NS NS NS NS NS		1/13/88		•	•		•			,	4 1
7/18/88 NS NS NS NS NS NS NS		7/18/AA		1	•					,	· • • • • • • • • • • • • • • • • • • •
CH/08/88 NS NS NS NS NS NS NS NS NS NS NS NS NS			NS								i
3 /03/89 NS NS NS NS NS NS		C3/03/89	NS						- 1 1 THE R. L.		
				· · · · · · · · · · · · · · · · · · ·	The state of the s	•		•		• 277.2 2 2 3 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	* 3. *

Motes:

ယ

in, out - influent and effluent samples

<1.0, BMDL, J - Present below quantitation limit.</p>

The quantitation limit was raised for diluted samples. $\ensuremath{\mathsf{NR}}$ Not requested.

NS - Not sampled.

(F) - Filter installed by EMS Resource Group for CSG

(f) - filter installed by homeowner; f1-softener

	Well Location/ sampling date	TCE		TCA	1, 1-DCE	TR 1,2-DCE	1,1-DCA	PCE	CHLOROFORM	1,2-DCA Quantitation Limit	·.·
	sampting date	in	out	in out	in out	in out	in out	in out	in out	in out	
-					3.5			40	40		
	9/15/84 6/04/87	<1.0 NS		NR NS	NR NS	NR NS	NR NS	NR NS	NR NS	NR 1.0	•
i~	10/14/87	NS	, e Na	NS	NS	NS	NS	NS	, NS	l NS	
	1/13/88	NS.		NS	NS	· NS	NS	NS	NS.	NS	
	7/18/88	NS		NS	NS .	NS	NS	NS	NS	NS .	
•	11/08/88	NS		NS NS	NS NS	NS NS	NS NS	NS NS	NS NS	NS NS NS NS NS NS NS NS NS NS NS NS NS N	
	3/03/89	NS:		100 mg	"	N.S			1 7		
ĺ				<i>'</i> • • • • • • • • • • • • • • • • • • •			A Section of				. :
7 5	9/15/84	<1.0	``.	NR	NR .	NR NR	NR	NR NR	NR NR	NR 3 1.0	
	6/04/87	NS .		NS	NS	NS NS	NS NS	NS NS	NS NS	NS NS	
	10/14/87 1/13/88	NS NS		NS NS	NS NS	NS	NS	NS	NS	NS NS	
	7/18/88	NS		NS	NS	NS	NS	NS	NS	NS I	•
4	11/08/88	NS		NS	NS	NS	NS	NS	NS NS	NS	
	3/03/89	NS	1.	NS	NS	NS	NS	NS	NS.	MS.	
- 1											
. 1	9/15/84	<1.0		NR	NR	NR	NR	NR	NR	NR 1.0	
	6/04/87	NS		NS	NS -	NS	NS	NS	NS	NS .	1.
	10/14/87	NS NS		NS.	NS NS	NS NS	NS NS	NS NS	NS NS	NS NS	
	1/13/88 7/18/88		.6	NS	NS	NS	NS	NS	NS	l. NS	:
	11/08/88	NS	/* r.	NS	NS	NS NS	NS	NS	NS	NS	
	3/03/89	NS	. :	NS	NS .	NS	NS	NS	NS .	NS	
ĺ	A STATE OF S	-	- ,	1.		154					
	9/15/84	<1.0		NR	NR	NR NR	NR	NR NR	NR	NR 1.0	
*	6/04/87	- NS		NS .	NS -	NS	NS	NS	NS	NS	
	10/14/87	NS		NS .	NS	NS NS	NS NS	NS NS	NS NS	NS NS	, ·
	1/13/88 7/18/88	NS NS		NS NS	NS NS	NS NS	NS	NS	NS	NS .	
	11/98488	NS		NS	NS	NS	NS	NS .	NS	NS JA V T. J.	
	3/03/89	NS	•	NS	NS	/ NS	NS	NS	NS	HS	
									10		
	9,057,84	<1.0		NR	NR .	NR	NR.	NR	NR	NR 1.0	
	6/84/87	NS		NS	NS	NS	NS	NS	NS .	NS AND AND AND AND AND AND AND AND AND AND	
	6/84/87 10/14/87 1/13/88	NS		NS	NS	NS	NS	NS	NS	NS	
4	1/15/88	NS		NS .	ŇS	NS NS	NS NS	NS NS	NS NS	NS NS	
	7 /48 /88 11 / 108/88	NS NS		NS NS	NS NS	NS	NS	NS	NS	NS	
	3/03/89	NS.		NS.	NS A	NS	· NS	· NS	NS	NS	
	-,,		ţ	•			74 yr	6.3	20		5

Notes:

in, out - influent and effluent samples
<1.0, BMDL, J - Present below quantitation limit.
The quantitation limit was raised for diluted samples. NR - Not requested.:

- NS Not sampled.
- (f) Filter installed by EMS Resource Group for CSG
 (f) filter installed by homeowner; f1-softener; f2-charcoal; f3-neutralizer
 ND Not detected at quantitation limit.

		<u> </u>							
	Well Location/ sampling date	TCE	TCA -	. 1,1-DCE - TR 1,2-	DCE 1,1-DCA	PCE	CHLOROFORM	1,2-DCA	Quantitation Limit
		in out	in out	in out in	out in out	in out	in out	in out	<u> </u>
	9/15/84	<1.0		200		1.40		. 4	, *
	6/04/87	NS	NR	NR NR		NR	NR	NR THE	1.0
	10/14/87	NS NS	NS NS	NS NS	NS	NS	NS	NS	
	1/13/88	NS	NS	NS () NS	NS	NS	NS	NS	
	7/18/88	NS	NS NS	NS S NS	NS	NS	NS	NS	•
-	11/08/88	NS		NS NS	NS NS	NS NS	NS	NS	
	3/03/89	NS	NS .	NS NS	NS NS	NS NS	NS NS	NS	
			77.		""	"3	NS	NS	•
•				j j					•
	3/15/89	ND	ND	ND ND	ND ND	ND	. ND	ND	1.0
	3,			13. 1 to 10.		1	MU	MD	1.0
	A, ·								
	9/15/84	23.0	NR	NR NR	NR	NR .	NR	NR .	1.0
	6/04/87	NS	ŃS	NS NS	NC	NS	NS	NS	
	10/14/87	NS	NS	NS NS	NS NS	NS .	NS	NS	
	1/13/88	NS	NS	NS NS	NS	NS	NS	NS	
	7/18/88	NS	NS	NS NS	NS.	NS	NS	NS	. 4 '
	11/08/88	NS.	NS	NS NS	NS	NS	NS	NS	
	3/03/89	NS	NS	NS NS	NS	NS	NS	NS	
						1			
			···			1.1	e la juli		•
	9/15/84	7.9 2.4	NR	1 100 TO TO	NR NR	NR	NR	NR	1.0
	6/04/87	NS	NS	, , , , , , , , , , , , , , , , , , ,		NS	NS	NS	
	10/14/87	NS	NS	NS NS	NS	NS	NS	· NS	•
	1/13/88	NS .	NS	NS NS	NS	NS	NS	· NS	20
:	7/18/88 11/08/88	NS	NS NS	NS NS	NS	NS	NS	NS	
	3/03/89	NS:	NS NS	NS NS	NS	NS	NS	NS	
	3/03/07	₩5	NS NS	NS NS	NS	NS	NS	NS	Denied access
						-		-	
	9/15/84	NS	NS	NS NS	NC 3		٠, <u>.</u>	2.3	
,	3/03/86	ND	12.0	NR ND	NS AN	NS NR	NS ND	NS	
	6/23/86	ND	<5.0	NR ND	NR NR	1 "" -		NR	1.0
	10/23/86	ND	ND	ND ND	ND ND	NR .	NR	NR.	5.0
	6/04/87	ND 3	4.1	ND ND		ND	ND	ND	1.0
1	119/14/87	ND.	1.0	, .	ND	, MD	<1.0	1 ND *12 /	.1.0
-	7/13/88	<1.0	5.0	ND ND	ND ND	ND	<1.0	ND	1.0
	7/18/88	NS	NS	NS NS	NS	ND	<1.0	ND	1.0
	7/18/88 1/08/88	NS	NS.	NS NS		NS NS	NS NS	NS	
	1 /03/89	NS	NS	NS NS	NS NS	NS	NS NS	NS NS	A A
•	0					ι (1 ₂ πο 1 ₂ 1 ₃ 1 ₄	· #3	₩3	

Moes:

 ω S in, out - influent and effluent samples
<1.0, BMDL, J - Present below quantitation limit. The quantitation limit was raised for diluted samples. NR - Not requested.

NS - Not sampled.

(F) - Filter installed by EMS Resource Group for CSG

(f) - filter installed by homeowner; f1-softener

	Well Location/ sampling date	TCE		TCA	`.	1,1-	DCE	TR 1,2	-DCE	1,1-DCA	PCE	CHLOROFORM	1,2-DCA	Quantitation Limit
		in	out:	l in	out		out	in	out	in out	in out	l in out	in out	1
			i	l .		ļ								
	9/15/84	<1.0	٠.	NR.	r '.		IR ·	NR.		NR.	NR.	NR NR	NR	1.0
	3/03/86	ND 4	,	ND		•	R>	ND		NR .	NR	NR NR	NR 1	1.0
	6/23/86	, ND		NR	:	: N	R.	NR.		NR	NR	NR (a	NR NR	5.0
٠.	6/04/87	•. •	ND	1	ND		ND	1.	ND	ND.	ND	ND.	ND ND	1.0
	10/14/87	, ND	1 z -	<1.0	; è		iD :	ND		ND	ND ND	<1.0	ND.	1.0
	1/13/88	· <1.0		<1.0	1.5	,	ID,	ND.	j 1993 N	ND:	. ND	<1.0	ND,	1.0
	7/18/88	NS (NS			S	NS.		NS.	NS	NS	NS	1
	11/08/88	NS		NS	• . •		is .	NS.		NS: -	"NS	To NS	NS -	
	3/03/89	S NS	· :	, NS	1 -	. N	IS .	NS	3 6	NS	NS:	NS.	NS	
				!	ng s	ļ.				Jan Barrey		1		
		-1, 3						- 4	- 0	ļ:	1		30 10 12	
	9/15/84	<1.0		NR			IR.	NR.		NR NR	NR	NR	NR	1:0
	6/04/87	NS		, NS			is.	NS		NS	NS	NS	NS	
	10/14/87	ŅS		NS NS			S	, NS		NS	NS	NS	NS	j .
	1/13/88	NS	_	NS			S	NS.		NS.	NS.	NS NS	NS _	ž.
	7/18/88	NS		NS.			S	NS		II. NS	NS.	NS	NS	
,	11/08/88	NS	` .	NS	*		IS	NS.		NS	NS **	NS	NS	1
•	3/03/89	NS	9 9 4	NS	?	N	IS .	NS		NS.	NS	NS	NS	[1.
	- Marian Committee	`.	,			ļ	- 4	1	•				1 82	1
					2 1	[' .						1		1
	9/15/84	<1.0	,, .	NR	1.		IR	NR.		NR.	NR NR	NR	NR	1.0
	6/04/87	NS		NS			IS. as	NS.		NS	NS A,	NS.	NS	
	10/14/87	. NS		NS			IS .	NS.		NS	NS	NS	NS.	
	1/13/88	NS		NS		,	IS .	NS		NS	NS	NS	NS	A A STATE OF THE S
	7/18/88	"NS		NS.			is) NS		NS	NS	NS	NS	
	11/08/88	NS,		NS		ŧ	IS	NS	,	NS	NS.	NS	NS NC	
	3/03/89	NS		NS	ř	! ` N	IS	NS.	,	NS	NS	NS .	Le NS :	<u> </u>
	·				•	!	7	` ' \						<u> </u>
	•			[]	. '	1	-		A 18			
	9/15/84	NO RESUL	15	NS		•	IS	NS		NS	NS	NS	NS	
	6/04/87	NS	٠,	NS		•	IS	NS		NS	NS	NS	NS	
	19414/87	NS		NS.		•	IS	NS		NS	l NS	NS	NS	<u> </u>
	1/13/88	NS	.:.,	NS.			IS	NS.		NS	NS	NS NS	NS	<u>[</u>
	7/18/88	NS.		· NS		•	IS	, NS		. NS	NS	NS	NS NS	
	1708/88	NS		NS	-	•	IS .	NS		NS.	NS	NS	l M2	
	G703/89	NS.	`	NS.	*-	- N	IS	. Pr. DNS	, ,	NS	NS NS	NS .	NS	late of the second
	\Box				3	`.				4	•			•

NN⊗:

in, out - influent and effluent samples A. .

<1.0, BMDL, J - Present below quantitation limit.

The quantitation limit was raised for diluted samples. NR - Not requested.

NS - Not sampled.

(F) - Filter installed by EMS Resource Group for CSG

(f) - filter installed by homeowner; f4-conditioner

SUMMARY OF RESIDENTIAL GROUNDWATER QUALITY ANALYSES, COMMODORE SITE, PA 1984-1989 (Concentrations in parts per billion.)

Well Location/	TCE	TCA	1,1-DCE	TR 1,2-DCE	1,1-DCA		20.00		···
sampling date	¥	104	1,1 DCE	IK 1,2-DCE	I, I-DCA	PCE	CHLOROFORM	1,2-DCA	Quantitation Limit
,	in ou	t in ou	in out	in out	in out	* * * * * * * * * * * * * * * * * * * *			
		.] 50	, ,,, ,,,	I III out	in∀ out	in⊹ out	in out	in out	•
9/15/84	<1.0	NR	NP	NR	NR		:22		
6/04/87	NS	NS	NS	NS NS		NR	NR	NR	1.0
10/14/87	NS	NS	NS NS		NS	NS	NS	NS	8
1/13/88	NS	NS	NS	NS	NS	NS	NS	NS	
7/18/88	NS '	NS:	NS	NS	NS .	NS	NS _.	NS	. .
11/08/88	NS .	NS	NS	NS	NS .	NS -	NS	NS	
3/03/89	NS	NS.	NS	NS NS	NS	NS	NS	NS ,	
		, ,,,	M.S	NS	NS	NS	NS	NS	•
		· 1	, ,	· · .	,				
9/15/84	<1.0	NR	17.				1	. 4	
3/03/86	5.0	ND.	NR NB	NR	NR	NR	NR	NR :	- 1.0
6/23/86	ND	<5.0	NR .	ND ND	NR	NR	NR .	NR '	, it.0
10/23/86	ND		NR	, ND	NR .	NR	NR,	NR %	5.0
6/04/87	ND.	ND ND	ND	ND	ND	ND ,	ND	ND I	1.0
10/14/87	<1.0		ND -	ND	ND	ND [ND	- ND	1.0
1/13/88	1.0	ND <1.0	ND S	ND .	, ND	ND.	ND	ND	1.0
7/18/88			<1.0	<1:0	ND:	<1.0	` <1.0	ND .	1.0
11/08/88	NS NS	NS	NS	NS	NS	NS	NS	NS .	
3/03/89		NS	NS	NS.	NS	NS	NS	NS	
3/03/69	NS	NS	NS	NS	NS	NS .	NS I	NS	
				_ :		•		. :	
									• • • • • • • • • • • • • • • • • • • •
9/15/84	140.0	NR	NR	NR I	NR I	NR	. NR	NR 5	1.0
3/03/86	173.0	170.0	NR	ND	NR	NR	NR	NR	1.0
6/23/86	59.0	44.0	NR :	ND	NR	NR Mini	NR I	NR I	5.0
6/04/87	70.0 1.8		17.0 <1.0	ND ND	2.3 ND	ND ND	ND ND	ND ND	1.0
10/14/87	74.0	80.0	13.0	'ND	1:0	<1.0	ND	ND	1.0
1/13/88	52.0	59.0	12.0	<1.0	2:0	<1.0	<1.0	ND	1.0
7/19/88	90.0	85.0	5.5	ND	6:5	ND	ND	ND	1.0; 20.0, TCE, TCA
11/08/88	78.0 ND	1	ND ND	ND ND	ND ND	ND NÔ	ND ND	400.0 450.0	10.0
3/03/89	62.0	46.0	18.0,	ND	2.6	ND	ND I	ND ND	1.0; 10.0, TCE, TCA
				f:	′ . I	. 1		, m	1.0, 10.0, ICE, ICA
		1		·,,		, 1°	* 15 g	<i>∰</i>	
9/15/84	210.0 <1.0		NR	NR	NR	NR I	NŘ 🖖	NR *	1.0
10/23/86	399.0 450.0	241.0 311.0	ND 35.0	ND ND	ND ND	ND ND	ND ND	ND ND	1.0
6/04/87	NS	NS	NS	NS	NS	NS .	NS.	NS ND	1.0
10/14/87	NS .	NS	NS	NS	NS	NS .	NS I	NS NS	
1 413/88	103.0 48.0	160.0 76.0	31.0 11.0	<1.0 <1.0	4.0 2.0	1.0.<1.0	- ,	* V =	
3/12/88 7/20/88	72.0		35.0	MD	4.0	<1.0		1. The second of the second of	1.0
7/20/88	230.0	300.0	17.0	ND NO	19.0	ND VI	ND ND	<1.0	1.0
1470 8/88	NS.	NS	NS	-NS			ND	ן שיי	10:0
GZD 4/89	91.0	99.0	28.0	ND	NS 12:0	NS .	NS	NS	
		Roselli (1. 20.0	A TOP AND A TOP A TOP AND A TOP A TOP AND A TOP A TOP AND A TOP A TOP AND A TOP A TOP A TOP A TOP AND A TOP A	12.0	ND	ND	ND	10.0
	et - influen			41% 1441				. e	e .

Notes:

in, out - influent and effluent samples

<1.0, BMDL, J - Present below quantitation limit.

The quantitation limit was raised for diluted samples.

NR - Not requested.

NS - Not sampled.

⁽F) - Filter installed by EMS Resource Group for CSG

⁽f) - filter installed by homeowner

ND - Not detected at quantitation limit.

				<u> </u>				. 11 1
Well Location/ sampling date	TCÉ	TCA	1,1-DCE	TR 1,2-DCE	1,1-DCA	PCE	CHLOROFORM 1,2-D	CA Quantitation Limit
•	in out	in out	in out	in out	in out	in out	in out in	out
	أراجي المنافق							
9/15/84	35.0 <1.0	NR NR	NR	NR	NR .	NR	NR NR	· · · · · · · · · · · · · · · · · · ·
3/03/86	15.0	ND	NR	20.0	NR	NR	NR NR	I
6/04/87	ND ND	<1.0 ND	ND ND	7.5 ND	ND . ND	ND ND	ND ND ND	•
10/14/87	7.0	<1.0	*<1.0	5.0	<1.0	<1.0	טאון מאון	
1/13/88	8.0	<1.0	<1.0 *	6.0	<1.0	<1.0	ND NO	1
7/19/88	4.7	ND	ND	12.0	ND	ND	ND ND	
11/08/88	4.6 ND	ND ND	ND ND	4.9 4.7	ND ND	" ND ND	ND ND 2.0	
3/04/89	5.6	ND	ND	11.0	ND -	ND 1	ND NO	1.0
	6.1		1		;			
		· .						
9/15/84	4.4	NR	NR	NR	NR	NR 🚁	NR NF	
6/04/87	2.3 ND	2.6 2.1	ND ND	4.4 ND	ND ND	ND ND	ND ND NE	
10/14/87	NS	NS	NS	NS	NS	NS	E NS NS	
1/13/88	NS	NS	NS	NS	NS	NS	NS NS	
7/19/88	ND	ND	ND	I ND	ND	ND	ND N	
11/08/88	1.0 ND.	ND 1.2	ND ND	2.4 2.4	ND ND	ND ND	ND ND NI	
3/06/89	2.5	ND	ND A	3.9	ND	ND	ND NO	D 1.0

Notes: in, out - influent and effluent samples

<1.0, BMDL, J. Present below quantitation limit.</p>
The quantitation limit was raised for diluted samples.

NR - Not requested.

NS - Not sampled.

(F) - Filter installed by EMS Resource Group for CSG

(f) - filter installed by homeowner

